

THE FANOUE Y BRIDGE

OFFICE OF

MUSKINGUM COUNTY ENGINEER

LOREN C. CAMP, ENGINEER

DON PAISLEY, ADMINISTRATIVE ASSISTANT

ZANESVILLE, DHID 49701

Situated in the State of Ohio, Muskingum County, Springfield Township, Twp. 16, Range 14, being part of the Southeast Quarter of Section 11, and more particularly described as follows:

Beginning at a stone at the south west corner of the south east Quarter of Section 11: thence with the south line of said quarter south 85 degrees 46 minutes 40 seconds east 1271.62 feet to an axle at the south west corner of the property now or formerly owned by Clyde Dutro and recorded in Deed Book 526 page 196 of the Deed Records of said County and State; thence north 4 degrees 22 minutes 45 seconds east 1378.42 feet to an iron pin in the center line of Chaps Run; thence south 83 degrees 23 minutes east 13.19 feet to a point in the center of Chaps Run, said point being the true place of beginning for the tract herein to be described; thence with the center of Chaps Run the following courses and distances: OFFICE COPY NOT RECORDABLE

North 79 degrees 51 minutes east 61.41 feet North 57 degrees 41 minutes east 170.56 feet

North 83 degrees 50 minutes east 155.64 feet

North 30 degrees 24 minutes east 72.56 feet

North 71 degrees 25 minutes east 30.37 feet;

thence leaving said Run south 6 degrees 37 minutes west 208.66





THE PAMOUS Y BRIDGE

MUSKINGUM COUNTY ENGINEER

LOREN C. CAMP, ENGINEER

DON PAISLEY, ADMINISTRATIVE ASSISTANT

ZANESVILLE, OHIO 43701

feet to an iron pin, passing through an iron pin at 50.00 feet; thence south 83 degrees 23 minutes east 316.87 feet to an iron pin on the west line of Woody Lane; thence with said west line south 4 degrees 28 minutes west 30.02 feet to an axle; thence leaving said west line north 83 degrees 23 minutes west 718.00 feet to the place of beginning and passing through an iron pin at 600.00 feet containing 1.219 acres more or less.

Prior Deed Reference Vol. 751 Pg. 106

This description written November 30, 1979 by Loren C. Camp Registered Surveyor No. 5843.

OFFICE COPY NOT RECORDABLE

