ROBERT HAVENS

Situated in the State of Ohio, County of Muskingum, Springfield Township, Part of the Southwest Quarter of Section 15, Township 12, Range 13, bounded and described as follows:

Being all of Robert and Dorothy Havens Volume 2223, page 665. Parcel No. 62-58-02-33-000.

Commencing at a stone found at the Southwest corner of Section 15; Thence South 86°37'40"East along Section line 1228.73' feet to a point in center of County Road 6; Thence along center of County Road 6 North 00°47'06"East 69.99' feet to a point at the Place of Beginning; Thence along center of said road North 00°19'41"East 206.20' feet to a point; Thence continuing along said centerline on a curve to the right having a radius of 478.34' feet an arc length of 79.33' feet (the chord of which bears North 05°04'47"East 79.24' feet) to a point; Thence South 85°40'42"East leaving County Road 6 and alond Ryan P LLC Volume 2045, page 639, 219.49' feet to a point in Moxahala Creek, passing a iron pin found 22.60' feet and a iron pin set at 153.00' feet; Thence South 08° 13'07"West 277.41' feet to a point in Moxahala Creek; Thence leaving Moxahala Creek North 88°10'19"West 187.50' feet to the Place of Beginning, passing a iron pin found at 41.96' feet and a Axle found at 172.50' feet. Containing 1.33 Acres more or less.

Bearings are based on the south line of Section 15, bearing South 86° 37'40"East.

Above description is based on a survey by R.L. Daniels Reg Surveyor# 5410, Mar-1, 2011, and is intended for legal transfer of property described and does not intend to describe all or any easements of record nor encroachments unless otherwise indicated.

Iron pins set are No. 5 reinforced bars 30" inches long with plastic I.D. Cap " RLS 5410".

Reference Volume 2223, page 665.


NOT RECORDABLE

DANIELS

JONAL STORY

PLAT OF SURVEY

Muskingum County, Ohio Township of Springfield Part of the Southwest Quarter of Section 15 Township 12, Range 13




Basis of Bearings

Bearings are based on the South line of Section 15. Bearing South 86 37'40"East. Bearings shown hereon are to an assumed meridan and are used to denote angles only.

Pertinent Documents And Sources of Data Used:

- 1. Deed references as shown
- 2. Survey by Charle Harkness PLS #6885 (5/7/2003) for Robert Grant
- 3. Surveys by Peter Dinan RLS # 5451
- (July 1997) & (Jan. 23, 1980) 4. Survey by Paul Dinan P.S. 6579 (Nov. 20, 2000)
- 5. Survey by John Marshall (Oct. 1, 1980)
- 6. Muskingum County tax maps.



S 86°37'40"E 1228.73'

Curve

Delta Angle 9°30'07"

Radius 478.34

Arc 79.33

Tangent 39.75

Chord 79.24

Chord Bearing N 5°04'47"E

LEGEND

- Iron Pin Set
- o Iron Pin Found
- Axle Found
- Stone Found

OFFICE COPY
R.L. Daniels Reg. Sur. DAD ABLE

Survey of Robert & Dorothy Havens Volume 2223, page 665 Parcel No. 62-58-02-33-000.

R.L. Daniels & Assoc. (740) 697-7480 61 Old Rainer Rd. Roseville Oh. 43777

Scale: 1" = 100'

Date: 03-01-11