

Robert Mason
11/2/92

Situated in the State of Ohio, County of Muskingum, Township of Union, Township 1, Range 5, part of the Southwest Quarter of Section 8, and bounded and described as follows:

Commencing at the Southwest corner of Section 8; thence North $1^{\circ} 46'$ West 113.59 feet to a point in the center of Interstate 70; thence along center of Interstate 70 on a 5729.58 foot radius curve to the right the chord of which bears North $74^{\circ} 31'$ East 1197.83 feet to a point; thence continuing along center of Interstate 70 North $80^{\circ} 31'$ East 133.51 feet to a point at the intersection of Mooseeye Road; thence along the center of Mooseeye Road the following three (3) courses and distances, North $29^{\circ} 29'$ West 661.23 feet to a point, North $31^{\circ} 03'$ West 210.00 feet to a point and North $23^{\circ} 26' 39''$ West 180.90 feet to a point, the place of beginning; thence leaving Mooseeye Road South $69^{\circ} 26' 34''$ West 227.14 feet to an iron pin passing an iron pin set at 30.00 feet; thence South $60^{\circ} 31' 00''$ West 54.74 feet to a point; thence North $29^{\circ} 29' 00''$ West 33.71 feet to an iron pin; thence South $60^{\circ} 31' 00''$ West along Robert Mason and R. Buchanan 354.15 feet to an iron pin passing an iron pin at 145.44 feet; thence South $29^{\circ} 29' 00''$ East 53.71 feet to a point; thence South $60^{\circ} 10' 37''$ West along K. LePage 301.11 feet to an iron pin found; thence North $2^{\circ} 24' 47''$ West along the West line of Section 8 320.35 feet to an iron pin set on the South line of Baltimore & Ohio Railroad; thence along the South right-of-way line North $71^{\circ} 07' 13''$ East 123.18 feet to a point; thence along said right-of-way on a 1658.82 foot radius curve to the left the chord of which bears North $60^{\circ} 23' 28''$ East 703.78 feet to a railroad spike set in Mooseeye Road; thence along Mooseeye Road the following three (3) courses and distances, South $28^{\circ} 12' 51''$ East 79.38 feet to a point, South $21^{\circ} 55' 49''$ East 79.54 feet to a point and South $18^{\circ} 05' 45''$ East 121.78 feet to the place of beginning, containing 4.51 acres more or less.

Being part of Auditor's Parcel Number 66-66-10-08-36-000.

Bearings are based on a survey by Peter Dinan, Volume 1052, Page 105.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.

Deed Reference: Volume 879, Page 212.

Survey Description By:

R. L. Daniels
Registered Surveyor No. 510

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY J. L. Nantz
11-04-92

