66-50-14-25-001 LIND SONDALL I'L

EXHIBIT "A"

Legal Description 3.8330 Acres

Situated in the Northwest Quarter of Section 14, Township 1, Range 5, U.S. Military Lands, Union Township, Muskingum County, Ohio and being a part of the 19.81 acre percei (by deed) of John L. & Anna Mae Wilson as described in Q.R. Volume 1136, Page 47 of the Muskingum County Recorder's Office, said Wilson being Muskingum County Auditor's Parcel No. 66-50-14-25-000 and being more particularly described as follows:

Beginning at a found 5/8" iron pin in the south line of said Northwest Quarter of Section 14, being South 82 deg. 14' 10" East, 694.17 feet from the southwest corner of said Quarter Section, thence leaving said half section line, with the southwest line of Wilson, and the northerly line of a 51.361 acre parcel (by deed) of D. Hallowell as described in O.R. Volume 1561, Page 255 and shown in a survey by W. J. Biedenbach and Assoc., North 63 deg. 02' 17" West, passing a found 5/8" iron pin on the old southeast R/W of Sundale Road (County Road No. 105) at 414.99 feet, crossing said Sundale Road, a total distance of 611.33 feet to a found 5/8" iron pin in the south Limited Access R/W of Interstate

Thence with said south L/A R/W, North 78 deg. 38' 25" East, 614.36 feet, no monumentation set;

Thence North 71 deg. 33' 33" East, 49.26 feet, no monumentation set;

Thence leaving said L/A R/W, by a new dividing line through said Wilson, South 11 deg. 40' 55" East, crossing said Sundale Road, and passing a set 5/8" iron pin at the new southeast R/W of Sundale Road at 70,00 feet, a total distance of 448.54 feet to a set 5/8" iron pin in the south line of said Quarter Section and the south line of said Wilson;

Thence with said south line, being the northerly line of said Hallowell, North 82 deg. 33' 19" West, 196.65 feet to the point of beginning, containing 3.8330 acres of land, more or less, being 0.663 acres in the R/W of Sundale Road as per ODOT, subject to all legal highways, easements, and restrictions

The above described tract being a part of Auditor's Parcel No. 66-50-14-25-000.

North based upon the a bearing of North 7 deg. 36' 54" East on the west line of Section 14 as per survey by W.J. Biedenbach and Assoc, for said Hallowell. Set iron pins are 5/6" rebar with caps marked R.M. Roberts \$-5803.

This description is a result of a field survey by Raymond M. Roberts, Ohio Registered Professional Surveyor No. S-5803, of Advanced Surveying, LLC, as performed in October, 2002. Job No. 02-5.
January 22, 2003
S0533WilsonR.dOFFICE COPY
NOT RECORDABLE

DESCRIPTION APPROVED FOR ALIOTOP'S TRANSFER

