DESCRIPTION OF SURVEY FOR WIJ WILLIAMS

JOB#1409-5

Situated in the State of Ohio, County of Muskingum, Township of Washington:

Being part of the Southeast Quarter, of Section #9, Township #1, Range #7, of the US Military District, **being part** of the W J Williams property recorded in Official Record Volume 1946, Page 482 of said county's deed records, known as Muskingum County **Auditor's Parcel Number 70-15-09-13-000**, and more particularly described as follows;

Commencing at the unmarked common comer for the Southeast and Southwest Quarters of said Section #9 and for the Northeast and Northwest Quarters of Section #12 of said Township and Range;

- TIE 1 THENCE North 02 degrees 56 minutes 20 seconds East 860.20 feet along the common line for said Southeast and Southwest Quarters of Section #9 to an iron pin (found at the Northwest corner of the New Bakery of Ohio, Inc. property recorded in Official Record Volume 1582, Page 117, passing an iron pin (found) at the Southwest corner of said New Bakery of Ohio, Inc. property at 60.00 feet;
- TIE 2 THENCE North 66 degrees 27 minutes 15 seconds East 955.00 feet into said Southeast Quarter and through said Williams property to an iron pipe (found) at the Northwest corner of the R Driscoll and S Camay property recorded in Official Record Volume 1684, Page 680, being the place of beginning for the property herein intended to be described;
- #1- THENCE North 31 degrees 39 minutes 35 seconds East 192.13 feet through said Williams property to an iron pin (set);
- #2- THENCE South 71 degrees 23 minutes 35 seconds East 597.82 feet continuing through said Williams property to an unmarked point in the centerline of Church Hill Road (County Road #110), passing an iron pin (set) at 569.85 feet;
- #3- THENCE South 40 degrees 32 minutes 40 seconds West 201.78 feet along said road and common line for said Williams property and for the J & P Ankrum property recorded in Deed Book Volume 1079, Page 177 to the unmarked Northeast corner of said Driscoll/Camay property, being in the intersection of said Church Hill Road and Adamsville Road (State Route #93);
- #4- THENCE North 71 degrees 23 minutes 35 seconds West 565.83 feet leaving said roads and along the North line of said Driscoll/Camay property to the place of beginning, passing an iron pipe (found) at 41.00 feet, containing 2.50 acres, of which 0.10 acres are within the right of ways for said roads.

The bearings within this description are based on State Plane Coordinate Grid (Ohio South 1983) derived from GPS Observations. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on November 17, 2006, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.

Charles R Harkness PLS #6885

CHARLES
HARKNESS
6885

APRILIP TOR CLOSURE

