

70-58-01-26  
2319 EAST PINE ✓

Being a part of the 3rd Quarter of Township one, Range seven,  
United States Military Lands, Washington Township, Muskingum County,  
Ohio and being further described as follows:

Commencing at a point marked by an existing stone at the South West corner of Lot number 3 of John C. Howard's Subdivision as recorded in Deed Book 9 page 394 of the Muskingum County Deed Records, said stone also being on the East line of the said 3rd Quarter, and is also a distance of 370.36 feet West of the South West corner of the Pleasant Grove School lot as marked by an existing axie; thence South 02 degrees 16 minutes 52 seconds East a distance of 1284.91 feet along the said last line of the 3rd quarter to a point marked by an existing iron nail, said point being on the North limited access right-of-way line of Interstate 70; thence North 81 degrees 00 minutes 01 second West a distance of 210.68 feet along the said South limited access right of way line to a point marked by an existing iron nail, said point being a distance of 1.5 feet right of centerline station 61+30 of said Interstate 70, as recorded in plat book 10 page 50 of the Muskingum County Plat Records; thence South 02 degrees 12 minutes 48 seconds East a distance of 527.40 feet to a point marked by an existing wood post, passing a point marked by an existing iron pin at 138.71 feet; thence North 87 degrees 31 minutes 28 seconds East a distance of 54.10 feet to a point marked by an existing iron nail; thence South 05 degrees 51 minutes 34 seconds East a distance of 590.46 feet to a point in the center of United States Route 40, passing a point marked by an existing iron pin (3/4 inch 1.0 pipe) at 501.00 feet; thence South 06 degrees 21 minutes 17 seconds West a distance of 25.52 feet along the said center of United States Route 40 to a point; thence North 02 degrees 51 minutes 20 seconds East a distance of 106.47 feet to a point marked by an existing iron pin (3/4 inch 1.0 pipe), passing a point marked by an existing iron pin (3/4 inch 1.0 pipe) at 45.23 feet; thence North 03 degrees 09 minutes 09 seconds West ~~g 0225 H 233.67~~ to a point marked by an existing Iron Pin; thence North 01 degrees 14 minutes 53 seconds West a distance of 120.97 feet to a point marked by an existing iron pin (3/4 inch 1.0 pipe), said point being the place of beginning of this tract; thence South 02 degrees 40 minutes 41 seconds East a distance of 510.70 feet to a point marked by a drill hole in a concrete retaining wall; thence South 75 degrees 00 minutes 18 seconds West a distance of 72.00 feet along the Northerly right-of-way line of United States Route 40, to a point marked by an iron pin (1/2 inch 1.0 pipe), passing a point marked by an existing concrete highway monument at 35.99 feet; thence North 05 degrees 11 minutes 34 seconds West a distance of 512.84 feet to a point marked by an iron pin (1/2 inch 1.0 pipe); thence North 72 degrees 29 minutes 02 seconds East a distance of 511 feet to the place of beginning.

Containing .017 more or less acres.


I hereby certify the above description to be correct as prepared by me this 2nd day of November 1982.

**OFFICE COPY  
NOT RECORDABLE**  
W.J. KLEINBACH  
KLEINBACH SURVEYOR #5718

OF WD  
11-23-82


See Plan No. 2

Southeast corner  
of Lot 23, Section  
HOWARD'S SUBDIVISION  
(L.B. & P. 394)



- ~ Existing Iron Pipe
- ~ Iron Pipe Sod Cover
- ① ~ Concrete Highway Mon.
- \* ~ Nail hole in Concrete Retaining Wall

Bearings are based on  
the previous survey of 0.53 acres  
(O.S.R. 1935)



Being a part of the 3rd Quarter of Township  
1, Range 1, United States Military Lands,  
Washington Township, Muskingum County, Ohio.

I hereby certify the above plat and survey  
to be correct as prepared by me, this 1st  
day of November 1982.  
  
W. J. Biedenbach  
W. J. BIEDENBACH  
R.L.C., SURVEYOR #5-16

**OFFICE COPY  
NOT RECORDABLE**

W. J. BIEDENBACH & ASSOC.  
Surveying & Mapping  
3120 Lisa Ln. Zanesville, Ohio 43701  
(614) 453-4850

Drawn by	ED	Date	11-1-82
Scale	1/8" = 10'	Checked by	ED
Job No.	1038-6-82	J. Gormley-Teters	