


SPEED STUDY DATA SHEET

 Date 10/05/06

 County MUS

 Municipality Muskingum County

 Highway name & number 0142 (MEADOW FARM CHURCH RD)

 Street classification STANDARD RURAL

Log point	* **	PHYSICAL CONDITION							* **	TRAFFIC CONTROL DEVICES				SPEED		ACCIDENTS	Test Runs
														85%	PACE		
0.6																	
0.5																	
0.4		○			CR 142 (OLD COOPERMILL RD)	Y			R2-1-35	T							
0.3							○										
0.2							○										
0.1																	
0.0		⊕			CR 71 (COOPERMILL RD)	Y			R1-1	T			R2-1-35				

Edge of berm | 4 | 11 | Edge of pavement | 11 | 4 | Edge of berm