DESCRIPTION OF SURVEY FOR CHANDLERSVILLE CHURCH OF CHRIST

JOB#1155

Situated in the State of Ohio, County of Muskingum, Township of Salt Creek:

Being within the platted area of Chandlersville recorded in Deed Book 1, Page 536, further being part of the Southwest Quarter of Section #13, and Southeast Quarter of Section #14, Township #13, Range #12, of the Congress Lands East of the Scioto River, **BEING PROPERTY CLAIMED BY THE CHANDLERSVILLE CHURCH OF CHRIST THROUGH DEED AND OCCUPATION**, deed references include Deed Book 761, Page 32, Deed Book 946, Page 252, and Deed Book 949, Page 237 of said county's deed records, known as Muskingum County **Auditor's Parcel Numbers 60-60-70-03-(07+08+09+10+11+12)-000**, and more particularly described as follows;

Beginning at an unmarked point in the center line of Chandlersville Roed (State Route #146), on the common line for said Sections #13 & #14, from which an iron pin (found) at the common Southern corner for said Sections #13 & #14, bears for reference South 00 degrees 34 minutes 50 seconds East 2334.37 feet, also from said place of beginning an iron pin (found) at the common Northern corner for said Sections #13 & 14, bears for reference North 00 degrees 34 minutes 50 seconds West 2973.09 feet;

- #1- THENCE North 75 degrees 00 minutes 00 seconds West 25.01 feet into Section #14 and along the conter line of seid State Route #146 to the unmarked intersection with the center line of Claysville Roed (State Route #313);
- #2- THENCE North 17 degrees 33 minutes 40 seconds East 183.05 feet along the center line of said State Route #313 to an unmarked point, from which a railroad spike (found) for reference bears South 05 degrees 57 minutes 20 seconds East 22.66 feet, and crossing into Section #13 at 77.38 feet;
- #3- THENCE along a curve to the right having a chord bearing North 52 degrees 30 minutes 10 seconds East 119.51 feet, a radius of 116.00 feet, and arc length of 125.55 feet, for seid State Route #313 to an unmarked point;
- #4- THENCE North 83 degrees 30 minutes 30 seconds East 148.39 feet continuing along said State Route #313 to an unmarked point at the intersection of seid State Route #313 and Bickford Lane (Township Road #817);
- #5- THENCE South 89 degrees 47 minutes 10 seconds East 65.82 feet leaving the conter line of said State Route #313 and elong the center line of said TR #617 to an unmarked point;
- #6- THENCE South 02 degrees 58 minutes 20 seconds West 147.59 feet leaving said TR #617 end along the extended West line of Lot #16 of Chandlersville recorded in Deed Book 1, Pege 536, as surveyed by Loren Camp PLS #5843 dated September 1, 1984 and by Dana Snouffer PLS #7543 dated February 10, 1998 to an iron pin (found), passing an iron pin (found) at 22.75 feet;
- #7- THENCE South 33 degrees 31 minutes 10 seconds West 16.90 feet to an iron pipe (found);
- #8- THENCE South 14 degrees 33 minutes 00 seconds West 188.47 feet to an unmarked point in the center of said State Route #146, passing an iron pipe (found) at 160.37 feet;
- #9- THENCE North 75 degrees 00 minutes 00 seconds West 284.51 feet elong the center line of said State Routa #146 to the place of beginning, containing 2.07 acres of which 0.53 acres are within the right of ways of said roads.

The bearings within this description are based on the North Line of State Route #146 (Chendlersville Road) as shown on the plat of Chandlersville Deed Book 1, Page 536. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on March 23, 2002, in accordance with Chepter 4733-37 of the Administrative Code, and is INTENDED TO BE USED FOR TITLE ACTION ONLY for the properly described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.

Change of Harkness PLS #6885

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

4-A.2M2



