Helen D. Dittmar 1333 Playford Avenue Zanesville, Ohio 5/13/91

Situated in the State of Ohio, County of Muskingum, Township 1, Range 7, part of Lot 1 of Blandy Hill Addition to the City of Zanesville, recorded in Plat Book 2, Page 19, bounded and described as follows:

Parcel One:

Commencing at an iron pin found at the Southeast corner of Lot 1; thence along the South line of said Lot 1 and North line of Playford Avenue South 90° 00' 00" West 45.00 feet to an iron pin found, the place of beginning; thence continuing along the South line of Lot 1 and Playford Avenue South 90° 00' 00" West 66.00 feet to an iron pin set; thence leaving Playford Avenue North 0° 00' 00" East 112.50 feet to an iron pin set on the South line of a private alley; thence along the South line of said private alley North 90° 00' 00" East 66.00 feet to an iron pin found; thence leaving said alley South 0° 00' 00" West 112.50 feet to the place of beginning, containing 0.170 acres more or less. All of Auditor's Parcel No. 80-84-39-02-15-000.

Parcel Two: 1332 PLAYFORD AUE

Commencing at an Iron pin found at the Southeast corner of Lot 1 of said addition; thence along the South line of said Lot 1 and the North line of Playford Avenue South 90°00' 00" West 111.00 feet to an iron pin set, the place of beginning; thence along the South line of Lot 1 and Playford Avenue South 90°00' 00" West 45.00 feet to an iron pin set; thence leaving Playford Avenue North 0°00' 00" East 112.50 feet to an iron pin set on the South line of a private alley; thence along the South line of said alley North 90°00' 00" East 45.00 feet to an iron pin set; thence leaving said private alley South 0°00' 00" West 112.50 feet to the place of beginning, containing 0.116 acres more or less.

All of Auditor's Parcel No. 80-84-39-02-14-000.

. 1

Bearings are based on the South Line of Lot 1 bearing North 90° 00' 00" East.

Iron pins set are No. 5 reinforcing bars 30 inches long with plastic I. D. caps.

Deed Reference: Wol. 969, Page 64 and Wol. 291, Page 297.


Survey & Description By:

R. Distered Surveyor No. 4510

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

BY St Mank. 5-17-91

R L DANIELS & ASSOC. 61 Rainer Rd. Rosevilla, Ohio 43777 Ph. (614) 697-7480



•IronPins Set No.5
Reinf Bars 30" Lg Plostic
I.D. Caps.
O IronPins Found.

Deed Res. Vol 969, P64 Vol 291, P297 Helen D. Dittmar
By RLDanox Reg Surveyor
No.5410 (Aly lov Bl.
Meshwig workwonty, TI, RT,
Ory Officers Ville, Part
Officer To Blandy Hill
Add Ition To Zanesville
PBZ, Page 19.

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

BY 17 17 and