Situated in the State of Ohio, County of Muskingum, Township of Jackson:

Being the Southeast Quarter, of the Southeast Quarter, of Section #15, Township #3, Range #9, of the US Military District, known as Muskingum County Auditor's Parcel Number 29-30-15-22-000, **being part of** the George Randall property described in deed reference Deed Book Volume 442, Page 265 of said county's deed records, **containing 41.81 acres**;

## ALSO GRANTED AN EASEMENT FOR INGRESS AND EGRESS

Also granted an easement for ingress and egress from Cannon Road (Township Road #316 through the Northwest and Northeast Quarters of the Northeast Quarter of Section #16, of said Township and Range to the South line of said Southeast Quarter, of the Southeast Quarter, of Section #15, and more particularly described as follows;

Beginning at a wooden post (found) at the common corner for the Southeast and Southwest Quarters of the Southeast Quarter of Section #15 and for the Northeast and Northwest Quarters of the Northeast Quarter of Section #16;

- #1- thence N 90 00 00 E 150.00 feet along the common lines for Sections #15 & #16 to an iron pin (set);
- **#2- thence** S 63 21 20 W 111.50 feet into the Northeast Quarter of the Northeast Quarter of Section #16 to an iron pin (set);
- #3- thence N 90 00 00 W 50.00 feet continuing through said Northeast Quarter of the Northeast Quarter of Section #16 to an iron pipe (found) on the common line for said Northeast and Northwest Quarters of the Northeast Quarter of Section #16, also being the Northeast corner of the T Householder property recorded in deed reference Deed Book Volume 802, Page 172;
- **#4- thence** S **89 58 20 W 562.99 feet** into said Northwest Quarter of the Northeast Quarter of Section #16 and along a line of said Householder property to an iron pipe (found);
- **#5- thence S 17 43 30 W 211.07 feet** along a line of said Householder property to an iron pipe (found);
- **#6- thence** S **80 37 40 W 86.32 feet** along a line of said Householder property to the center of said Cannon Road, passing an iron pipe (found) at 55.99 feet;
- **#7- thence** N 09 31 30 W 269.10 feet along said road to the common line for said Sections #15 & #16;
- **#8- thence** N 90 00 00 E 756.60 feet leaving said road and along the common line for said Sections #15 & #16 to the place of beginning, passing an iron pin (set) at 50.67 feet.

The bearings within this description are based on an assumed meridian and are for angular purposes only. Bearings are shown in a format of Degrees, Minutes, and Seconds. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on April 8, 2000, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.

OFFICE COPY CHARLES PLANTED TO THE COPY OF THE COPY OF

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER BY

7-12-2000

