


**SITUATED IN**


The State of Ohio, County of Muskingum  
 City of Zanesville, and being a part of Lot 11,  
 and 12, of the subdivision of "Maplewood" as  
 delineated in Plat Book 2, Page 45.

**LEGEND**



- ⊙ Iron Pin Set, 5/8" rebar
- Iron Pin Found
- Pipe Found



DETAIL "B"



DETAIL "C"



DETAIL "A"

Iron Pin Found at the Southeast Corner  
 of Lot 11, of "Maplewood" Subdivision as  
 delineated in Plat Book 2, Page 45 of  
 the Muskingum County Records.

**BASIS OF BEARING**

Bearings are based on the south line of the  
 subdivision of "Maplewood" as being N86°W  
 as depicted in Plat Book 2, Page 45.

**REFERENCES**


- OR 1867-313
- DR 960-295
- DR 725-244
- DR 1157-582

**PARCEL NO.**

All of: 80-84-05-03-22-000(±0.20 ac.)

DESCRIPTION APPROVED  
 FOR RECORDS TRANSFER

*[Signature]*  
 7-29-04



7-29-04  
 Date

**GRAPHIC SCALE**



( IN FEET )  
 1 inch = 50 ft.

Project No.: 84-05-MMG



Linn Engineering, Inc. 740-452-7434  
 Civil Engineering Consultants  
 P.O. Box 2086 Zanesville, Ohio 43702-2086