PAVILL # 13-40-03-25-001 MA

Robert V. Miller 10/10/88

Situated in the State of Ohio, County of Muskingum, Township of Clay, T 14, R 14, part of the Northeast Quarter of Section 3 and bounded and described as follows:

Beginning at an iron pin found at the Northeast corner of the Hostheast Quarter of Section 3; thence South 89 16' West 317.00 feet to an iron pin set; thence South 0' 44' 00" East 150.00 feet to an iron pin set; thence North 89' 16' 00" East 247.99 feet to the center of Gills Hollow Road passing an iron pin set at 217.99 feet; thence along center of Gills Hollow Road North 34' 10' 00" East 38.05 feet; thence North 27' 17' 00" East 99.77 feet along center of road; thence leaving center of Gills Hollow Road North 0' 00' 00" East 30.71 feet to the place of beginning, containing 1.00 acres more or less.

Bearings are based on the North line of the $\it Northeast$ Quarter of Section 3 bearing South 89 $^{\rm O}$ 16' 00" West.

Being a part of Auditor's Parcel No. 13-13-40-03-25-000.


Survey & Description of

R. Daniels Registered Surveyor No. 5410

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

10-12-88

R L DANIELS & ASSOC. 61 Rainer Rd. Roseville, Ohio 43777 Ph. (614) 697-7480



· Iron Pin Set [©] Iron Pin Found

Surply Of Part Of Robert
OFFICE Diller Deperty 10/10/88
OFFICE Diller Deperty 10/10/88
OFFICE Diller Deperty 10/10/88
NOT Plant 5410
Muskingum County, Clay
Township, T14, R14, Part
Of The N.E. Qtr. Sections
Part Of Parcel No.
13-13-40-03-25-000

DESCRIPTION APPROVED FOR AUDITOR'S TRANSFER

10-12-88