TERRY J. FINLEY SURVEYING & MAPPING

155 Mockingbird Hill, Zanesville, OH 43701 Phone or FAX (740) 454-8721

Ohio Registered Surveyor #S-7222

TRACT #2 63.4243 Acres

Situated in the State of Ohio, County of Muskingum, Township of Licking, and being part of Quarter Township 1, Township 2, Range 9, also, being part of Lots #3 & #4 of Roberts Survey, and being part of those lands intended to be described in Deed Volume 1122, page 579; being further bounded and described as follows:

Commencing at the southwest corner of the Southwest Quarter of Section 5, Township 2, Range 8, thence, along the Licking Township line, North, 02 degrees - 00 minutes - 11 seconds East, 44.50 feet to a point; thence, North 89 degrees - 04 minutes - 21 seconds West, 671.48 feet to a corner post at the true point of beginning for the parcel herein intended to be described;

THENCE, North 89 degrees - 21 minutes - 12 seconds West, 516.52 feet to an iron pin set;

THENCE, South 00 degrees - 48 minutes - 20 seconds West, 409,52 feet to an iron pin set;

THENCE, North 88 degrees - 46 minutes - 27 seconds West, 1470.80 feet to an iron pin found on the west line of Lot #4;

THENCE, North 01 degrees - 55 minutes - 36 seconds East, 1240.63 feet to a point in the center of Old Stagecoach Road (Township Road #304), passing an iron pin set at 1210.63 feet;

THENCE, along said road, the following ten (10) courses and distances:

- 1) North 67 degrees 15 minutes 55 seconds East, 42.66 feet to a point;
- North 82 degrees 45 minutes 57 seconds East, 103.54 feet to a point;
- 3) North 56 degrees 51 minutes 38 seconds East, 112.35 feet to a point;
- 4) North 54 degrees 57 minutes 07 seconds East, 103.89 feet to a point;
- 5) North 76 degrees 05 minutes 47 seconds East, 190.79 feet to a point;
- 6) North 76 degrees 44 minutes 32 seconds East, 140.48 feet to a point;
- 7) North 74 degrees 45 minutes 48 seconds East, 209.07 feet to a point;
- 8) North 76 degrees 33 minutes 54 seconds East, 332.10 feet to a point;
- 9) North 80 degrees 23 minutes 31 seconds East, 337.83 feet to a point;
- 10) North 78 degrees 56 minutes 37 seconds East, 80.27 feet to a point

THENCE, leaving said road, South 01 degrees - 59 minutes - 47 seconds West, 323.59 feet to an iron pin found, passing an iron pin found at 20.39 feet;

THENCE, North 88 degrees - 44 minutes - 44 seconds East, 500.95 feet to an iron pin found;

THENCE, South 02 degrees - 09 minutes - 08 seconds West, 376.27 feet to a corner post;

THENCE, South 89 degrees - 10 minutes - 30 seconds West, 75.48 feet to a corner post;

THENCE, South 02 degrees - 41 minutes - 19 seconds West, 611.45 feet to the point of beginning, and containing 63.4243 acres more or less.

Subject to all legal highways and easements of record whether recorded or implied.

Bearings described herein are based upon assumed azimuth and to be used for angle purposes only.

Iron pins set are 5/8" rebar with yellow identification cap (Finley S-7222).

Being part of Auditor's Parcel #35-10-41-34-000 - 60,0236 ac, with 1.1648 ac, remain part of Auditor's Parcel #35-10-41-16-000 - 3.4007 ac, with \$67500 ac, remain

This description, written on March 14, 2002, is based on an actual survey of the premises by

Terry J. Finley, Ohio Registered Survey

TE OF ONE TERRY 1 Registered Surveyor #S-72 FINLEY

LUMBORATION APPROVED LOG AUSTORY (RASISFER

TERRY J. FINLEY SURVEYING & MAPPING

155 Mockingbird Hill, Zanesville, OH 43701 Phone or Fax (740) 454-8721

State: OHIO

County: MUSK INGUM

City:

Subdivision: ROBERTS SURVEYING RECORD FOUND]

Township: LICKING Plat Book:

Page:

Lot #: PT. 4 AND 3

Section: PT.QTR.TWP.1,1-2,R-9


Deed Volume: 11.22

Page: 579 PT.

Bearings shown herein are based upon: ASSUMED AZIMUTH

SURVEY PLAT FOR; EMERSON DUNFUE PROPERTY

<u>TRACT NO. 2</u>



LEGEND:

Iron pin set (5/8" rebar w/cap)

O__ lron pin found

Stone found

Axle found ♠ ₽₽2

Railroad spike found

AUDITOR'S PARCEL #: PART 35-10-41-34-000

1.1649 AC. REMAINING

PART 35-10-41-16-000

3.4802 AC.

56.7500 AC. REMAINING

This plat drawn on MARCH 12 on on octual survey of the premises,