


LINE	BEARING	DISTANCE
L1	S 13°14'07" W	80.32'
L2	S 39°46'46" W	45.15'
L3	S 51°43'09" W	55.24'
L4	N 75°37'26" W	46.60'
L5	S 45°43'12" W	48.96'
L6	S 01°17'28" W	52.81'
L7	S 13°38'57" E	71.79'
L8	S 07°00'29" W	56.06'
L9	S 10°38'35" E	73.16'
L10	S 45°33'18" E	81.94'
L11	S 22°23'01" E	112.18'
L12	S 07°46'19" E	82.38'
L13	S 06°15'06" W	93.49'
L14	S 18°20'08" W	40.18'

POB: Iron Pin found on the Northwest Corner Section 1, Township 3, Range 5, USML, Monroe Township, Muskingum County, Ohio

ABK Investors, LLC
OR 2754-254
12.117 ac.
(42-30-01-16-000)

ABK Investors, LLC
OR 2754-254
16.278 ac.
(42-30-01-15-000)

Note #1.



Holmes Limestone Company
DR 1151-657
Tract Two
(42-30-01-09-009)

LEVI BAKER
OR 2944-672
±16.409 ac.
All of 42-30-01-03-000

ABK Investors, LLC
OR 2766-570
10.264 ac.
(42-30-01-01-006)

LEVI BAKER
OR 2944-680
± 0.980 ac.
All of 42-30-01-04-000

DESCRIPTION
APPROVED

By: *[Signature]*

Holmes Limestone Company
DR 1151-657
Tract One
Parcel 2
(42-30-01-09-011)

SITUATED IN

The State of Ohio, County of Muskingum
County, Township of Monroe Township,
Northwest Quarter of Section 1, T-3, R-5,
USML.

BASIS OF BEARING

Bearings are based on the Ohio State
Plane Coordinate System, NAD83, South
Zone, Grid North, as per GPS
observations made 11/12/20

LEGEND

- Iron Pin Found, 5/8" rebar
- ⊙ Iron Pin Set, 5/8" w/cap LINN #7113
- Fence
- P.O.B. Place of Beginning
- P.P.O.B. Principal Place of Beginning

REFERENCES

As shown.
Survey by Thomas Wayne Taylor,
PS #7053, dated 12/28/99.

PARCEL NUMBER SUMMARY

All of 42-30-01-03-000 ±16.409 ac.
All of 42-30-01-04-000 ± 0.980 ac.
Total ±17.389 ac.

NOTES

- There is a gap of unknown ownership
bounded by ABK Investors, LLC (OR
2754-254) on the west and north and
Levi Baker (OR 2944-672) on the
south and east.

OFFICE COPY
NOT RECORDABLE

Timothy H. Linn, PS
Reg. Surveyor No. 7113



Linn Engineering, Inc.
Civil Engineering Consultants
P.O. Box 2086 Zanesville, Ohio 43702-2086

740-452-7434