

DESCRIPTION OF SURVEY FOR TIM RASOR

JOB#1369-1

Situated in the State of Ohio, County of Muskingum, Township of Washington:

Being part of the Southeast Quarter, of Section #9, Township #1, Range #7, of the, US Military District, **being part of the T Rasor property** recorded in Deed Book Volume 1144, Page 790 of said county's deed records, further being known as Muskingum County **Auditor's Parcel Number 70-15-09-33-001**, and more particularly described as follows;

Beginning at an iron pin (found) at the common corner for the Southwest and Southeast Quarters of Section #9 and for the Northeast and Northwest Quarters of Section #12 of said Township and Range; **THENCE South 86 degrees 51 minutes 45 seconds East 1010.91 feet** along the common line for said Sections #9 and #12 to an unmarked point in the centerline of Adamsville Road (State Route #83); **THENCE along a curve to the right having a chord bearing North 09 degrees 35 minutes 20 seconds East 200.98 feet**, a radius of 1295.41 feet, and arc length of 201.18 feet, into said Southeast Quarter of Section #9 and along the centerline of said road to an unmarked point; **THENCE along a curve to the right having, a chord bearing North 18 degrees 22 minutes 10 seconds East 167.98 feet**, a radius of 2064.91 feet, and arc length of 168.03 feet, continuing along said road to an unmarked point; **THENCE North 18 degrees 42 minutes 00 seconds East 486.39 feet** continuing along said road centerline to the unmarked common corner for said T Rasor property and for the R & B Schley property recorded in Deed Book Volume 1149, Page 743, being the place of beginning for the property herein intended to be described;

- #1- **THENCE North 18 degrees 12 minutes 25 seconds East 92.16 feet** along said road centerline as surveyed by Dana Snouffer PLS #7543 dated October 1997 to an unmarked point;
- #2- **THENCE North 25 degrees 51 minutes 40 seconds East 73.28 feet** continuing along said road center and Snouffer survey to an unmarked point;
- #3- **THENCE North 31 degrees 12 minutes 40 seconds East 46.00 feet** continuing along said road center and Snouffer survey to an unmarked point;
- #4- **THENCE North 39 degrees 56 minutes 40 seconds East 46.38 feet** continuing along said road center and Snouffer survey to an unmarked point;
- #5- **THENCE North 46 degrees 33 minutes 40 seconds East 44.89 feet** continuing along said road center and Snouffer survey to an unmarked point;
- #6- **THENCE South 65 degrees 06 minutes 45 seconds East 371.97 feet** leaving said road and through said T Rasor property to an iron pin (set), passing an iron pin (set) at 35.00 feet;
- #7- **THENCE South 18 degrees 40 minutes 40 seconds West 134.84 feet** continuing through said T Rasor property to an iron pin (set) on the common line for said T Rasor and Schley property;
- #8- **THENCE North 88 degrees 45 minutes 15 seconds West 441.92 feet** along the common line for said T Rasor and Schley properties to the place of beginning, passing an iron pin (set) at 411.42 feet **containing 2.03 acres.**

The bearings within this description are based on State Plane Coordinate Grid (Ohio South 1983) derived from GPS Observations. Iron pins (set) are 5/8" rebar with identification caps (C.R.Harkness P.L.S.6885).

This description was written by Charles R. Harkness Professional Land Surveyor #6885 from an actual survey completed on July 14, 2004, in accordance with Chapter 4733-37 of the Administrative Code, and is intended to be used for the legal transfer of the property described and does not intend to describe all or any easements of record, nor encroachments unless otherwise indicated.

OFFICE COPY  
NOT RECORDABLE

Charles R. Harkness PLS #6885

DESCRIPTION APPROVED  
FOR AUDITOR'S PURPOSES

BY ALB

7-19-2004

