

William E. Hittle
4010 Chandlersville Road
4/11/88

Situated in the State of Ohio, County of Muskingum, Township of Wayne, T 12, R 13, part of the Northeast Quarter of Section 10 and bounded and described as follows:

Commencing at the Southwest corner of the Northeast Quarter of Section 10; thence North $90^{\circ} 00' 00''$ East on section line 415.00 feet to the Southwest corner of Lot Four (4) of Liggitt Subdivision, Plat Book 12, Page 67; thence along Lot Four (4) North $1^{\circ} 09'$ East 200.37 feet to an iron post found the place of beginning; thence North $89^{\circ} 19' 14''$ West 189.41 feet to an iron pipe found; thence North $1^{\circ} 15' 35''$ East 478.75 feet to an iron pipe found on the South line of Route 146; thence South $84^{\circ} 59' 41''$ East along Route 146 119.97 feet to an iron pipe found; thence South $1^{\circ} 33' 53''$ West 178.58 feet to an iron pipe found; thence South $88^{\circ} 17' 19''$ East 70.09 feet to an iron pipe found; thence South $1^{\circ} 09'$ West 289.87 feet to the place of beginning, containing 1.764 acres more or less.

Bearings are based on the South line of the Northeast Quarter of Section 10 bearing North $90^{\circ} 00' 00''$ East.

Being all of Auditor's Parcel No. 73-73-27-02-34-000.

Survey & Description By:

**OFFICE COPY
NOT RECORDABLE**
R. L. Daniels
Registered Surveyor No. 5410

DESCRIPTION APPROVED
FOR AUDITOR'S TRANSFER

BY J. L. Daniels
4-13-88