85-27-02-16-000



88 W. Church Street

Newark, Ohio 43055

740.345.4700



An Ohio EDGE Certified Firm



1900 Crown Park Court Columbus, Ohio 43235 614.914.5543

LEGAL DESCRIPTION OF A 0.126 ACRE LOT SPLIT July 8, 2014 Page 1 of 2

Situated in the State of Ohio, Couny of Muskingum, City of Zanesville, being part of Lot 5 and a part of two vacated alleys in Fenton's Subdivision, as recorded in Plat Book 4, Page 21, said Lot 5 being the property conveyed to Zanesville Welfare Organization and Goodwill Industries, Inc. by Official Record 2446, Page 121 of the Muskingum County's Recorder's Office, (being part of Auditor's Parcel Number 85-27-02-15-000), and said alley being vacated by Ordinance No. 13-75, and being more particularly described as follows:

Beginning for Reference at a 5/8" Rebar Found at the northeast corner of Lot 7 of Fenton's Subdivision, said point being in the southerly right-of-way line of Brookover Avenue (50° wide), thence along the southerly right-of-way line of Brookover Avenue and the northerly lines of Lots 7, 6, and 5, North 86 degrees 00 minutes 00 seconds West, 125.02 feet to an Iron Pin Set at the True Point of Beginning of the parcel herein described, said point being 25.00 feet easterly from the northwest corner of said Lot 5, and in the northerly line of said Zanesville Welfare Organization and Goodwill Industries, Inc. property;

Thence crossing said Zanesville Welfare Organization and Goodwill Industries, Inc. property, South 03 degrees 59 minutes 11 seconds West, 171.23 feet to an Iron Pin Set in the southerly line of said vacated alley running east and west (10' wide), said point being in the northerly line of the property conveyed to said Zanesville Welfare Organization and Goodwill Industries, Inc. by Deed Book 1152, Page 537;

Thence along the northerly line of said Zanesville Welfare Organization and Goodwill Industries, Inc. property (D.B. 1152-537), North 87 degrees 46 minutes 45 seconds West, 32.06 feet to an Iron Pin Set at the extension of the centerline of said vacated alley running north and south (14' wide);

Thence along the centerline of said vacated alley, North 04 degrees 00 minutes 00 seconds East, 172.22 feet to a Railroad Spike Found (N-0.02', E-0.07') on the southerly right-of-way line of Brookover Avenue;

Q5-27-02-16-000 A

LEGAL DESCRIPTION OF A 0.126 ACRE LOT SPLIT July 8, 2014 Page 2 of 2

Thence along the southerly right-of-way line of Brookover Avenue, South 86 degrees 00 minutes 00 seconds East, 32.00 feet to the True Point of Beginning, containing 0.126 acres more or less, passing the northwest corner of Lot 5 at 7.00 feet (referenced by a 5/8" Rebar Found (N-0.19', E-0.19')). Subject to any and all easements, right-of-ways, conditions and restrictions of record. All Iron Pins Set are 5/8-inch by 30-inch rebar with yellow identification caps labeled "Smart Services". BEARINGS SHOWN HEREON ARE BASED UPON THE SOUTHERLY LINE OF BROOKOVER AVENUE AS BEING SOUTH 86 DEGREES 00 MINUTES 00 SECONDS EAST AS SHOWN ON THE PLAT OF FENTON'S SUBDIVISION, AND ARE INTENDED TO BE USED ONLY FOR DETERMINING ANGLES. This description was prepared by Smart Services, Inc. in May 2014 and is based upon actual field measurements.





G:\PROJECTS\2014 Projects\637801 - TGC - 2160 Maple Avenue Combination\Maps-Plans-Drawings\description\637801-description.doc

PREPARED AS A COOPERATIVE EFFORT BETWEEN SMART SERVICES, INC. AND TGC ENGINEERING, LLC 1310 SHARON COPLEY ROAD, P.O. BOX 37, SHARON CENTER, OHIO 44274 ~ PHONE: 330.590.8004 TGC JOB NO. 1439

APPROVED BY CITY PLANNING COMMISSION, ZANESVILLE, OHIO; NO PLAT REQUIRED

8-19-14

DESCRIP APPRO By

